

Patio Refurbishment & All Paving Maintenance



Case Study

Marshall's Limestone Patio, Bolton, Lancashire

This stone circle and patio area at a private residence in Bolton, Lancashire, was laid using Marshall's limestone slabs and granite setts. It was only five years old and generally in good condition, but the pointing had already failed twice. The homeowners liked to keep their patio area in pristine condition, and used their jet-washer to keep it clean.

Luckily they contacted specialist paving contractors CR Services, who immediately recognised the cause of the pointing problems, and informed them that the 1-part jointing compound that had been used was not tough enough to withstand frequent direct jet-washing.

CR Services recommended the joints be cleaned and the pointing be replaced with GftK's vdw 850+, which is a 2-part epoxy paving joint mortar, supplied by NCC Streetscape, and ideal for natural stone paving. It is applied by wet slurry techniques, and will harden even in the cold and wet, ideal with the UK weather, and importantly, will fully resist regular jet-washing.

Prior to grouting, the area was again jet-washed and all the old pointing removed. It was then cleaned using NCC Black Spot and Green Growth Remover, before quickly repointing with GftK vdw 850+.

The crew from CR Services completed this project, leaving the owners delighted with their patio which was now better than new thanks to CR Services and GftK high performance professional jointing.

Patios & Terraces

Type of Stone
Marshall's Limestone Slabs
& Granite Edging Setts

Type of Paving
Slabs/Setts

Call CR Services
Office: **0161 905 3497**
Mobile: **0781 844 8330**
www.patior refurbishment.co.uk



CRSERVICES