

Patio Refurbishment & All Paving Maintenance



Case Study

Large Sandstone Patio, Northwich, Cheshire

The large, very dirty sandstone patio and cobbled area at this private residence in Northwich was badly in need of refurbishment. The cement jointing mortar was cracked and failing and there was an extensive amount of difficult to remove, lichen 'black spots' in the surface pores of the slabs, completely spoiling the appearance of this once attractive area.

Specialist paving contractor CR Services were approached and recommended GftK's vdw 850+, a tough, non-staining, 2-part epoxy paving mortar, supplied in the UK by NCC Streetscape. Apart from its toughness, one of the advantages of vdw 850+ is the speed of application, a big plus for this extensive project, with the large patio covering more than 235m².

After remedial works to remove the old jointing, the paving was jet-washed and then the surfaces treated with NCC Black Spot and Green Growth Remover, which brought the natural stone back to its original beauty.

Although it was raining at the time booked for the job, this was no problem when using GftK's vdw 850+, as it is applied by wet-slurry techniques from a standing position, meaning that during application, the wetter, the better! In fact, despite the inclement weather, the whole project was completed in a week!

Patios & Terraces

Type of Stone
Sandstone

Type of Paving
Slabs/Flags

Call CR Services

Office: **0161 905 3497**

Mobile: **0781 844 8330**

www.patior refurbishment.co.uk



CRSERVICES