

# Patio Refurbishment & All Paving Maintenance



## Case Study

### Patio & Pathways, Oldham, Greater Manchester

This intricately designed patio and path in Oldham had been down for many years and was in desperate need of some loving care! The reconstituted stone paving slabs were suffering badly from unsightly heavy grime and difficult to remove lichen 'blackspots', plus the original sand and cement pointing was cracked and failing.

Specialist paving contractors, CR Services were contacted and asked for advice and to provide the best solution to replace the failing mortar and to carry out the refurbishment. They advised replacing the failed cement mortar with GftK vdw 850+ paving joint mortar from NCC Streetscape, which is a high performance 2-part epoxy mortar, that is ideal for all types of paving, including reconstituted and natural stone.

Prior to application of GftK's vdw 850+, the CR Services crew removed all the defective concrete pointing and then the patio and paths were jet-washed and cleaned using high performance NCC Black Spot and Green Growth Remover.

The homeowners were delighted with their choice of CR Services whose advice and skill has returned their patio to not only looking as good as new but in fact tougher and more sustainable, allowing them to safely jetwash going forward.

#### Patios & Terraces

**Type of Stone**  
Reconstituted Stone

**Type of Paving**  
Slabs/Flags

**Call CR Services**

Office: **0161 905 3497**

Mobile: **0781 844 8330**

[www.patior refurbishment.co.uk](http://www.patior refurbishment.co.uk)



**CRSERVICES**