

# Patio Refurbishment & All Paving Maintenance



## Case Study

### Porcelain Patio Refurbishment, Bury, Lancashire

The owners of this private residence in Bury were disappointed that, although less than a year old, the original pointing on their white porcelain patio, with dark grey Brazilian slate sett edging, was already failing and coming out. Also the jointing compound used for the pointing had left unsightly staining to the edge of the tiles, giving an unwanted 'picture frame' effect.

They contacted specialist paving contractors, CR Services, who immediately knew exactly what to do to remedy the situation! Firstly they jet-washed the patio to remove most of the failed jointing, and any remaining residue was brushed from the joints. The porcelain slabs were then cleaned with NCC Porcelain Intensive Cleaner which removed the staining from around the tile edges.

The CR Services crew regouted the porcelain patio with GftK's vdw 815+, a 2-part, high performance, non-staining, paving jointing mortar, especially designed for high performance in narrow joints. This also resistant to frequent jet-washing.

The delighted homeowners now have a beautiful porcelain patio, in better condition than when first laid, and that will easily stand up to the intended heavy usage for many years to come.

#### Patios & Terraces

##### Type of Paving

White Porcelain Tiles

##### Call CR Services

Office: 0161 905 3497

Mobile: 0781 844 8330

[www.patior refurbishment.co.uk](http://www.patior refurbishment.co.uk)



**CRSERVICES**