

Patio Refurbishment & All Paving Maintenance



Case Study

Driveway Refurbishment, Preston, Lancashire

This private driveway in Preston, Lancashire is constructed with granite setts, and receives a lot of harsh exposure to de-icing salts from both passing traffic and also from being used for vehicle standing throughout the year. As a result the previous replacement cement joints were cracked, breaking up, and in places, lost altogether, causing damage to the stone bedding, further exacerbating the problems.

The homeowners approached specialist paving contractors CR Services to help them with a solution, and based on past experience and successes they immediately proposed GftK's high performance vdw 850+ Paving Joint Mortar from NCC Streetscape. This 2-part epoxy joint mortar is slurry applied so flows easily into the joints where it self compacts, and is designed specifically to accommodate this kind of heavy exposure and traffic.

The team at CR Services removed all the failing cement joints and re-bedded any loose granite setts. The driveway was then cleaned using NCC Dirt & Grime Remover followed by new jointing with vdw-850+, which was completed quickly and efficiently. The homeowners were delighted with the finished result, knowing that their completed driveway was now fit for purpose, well into the future.

Driveways

Type of Stone
Natural Granite

Type of Paving
Setts/Cobbles

Call CR Services

Office: **0161 905 3497**

Mobile: **0781 844 8330**

www.patirefurbishment.co.uk



CRSERVICES