

Patio Refurbishment & All Paving Maintenance



Case Study

Indian Sandstone Patio, Wilmslow, Cheshire

These Indian Sandstone Patios and Pathways were a lovely colour, but after only two years' service the original sand and cement pointing was literally crumbling away – most likely due to residual water changing the original water:cement ratio in the joint leading to cracking and frost damage – difficult to avoid with cement materials in the UK weather.

CR Services knew just how to fix this problem by replacing the failing sand and cement grout with a 2-part epoxy based paving joint mortar from NCC Streetscape. This is wet slurry applied with even more water and therefore not sensitive to the unpredictable and changeable British weather.

The surfaces were first cleaned using NCC Black Spot & Green Growth Remover, the old cement joint mortar was removed and the new epoxy paving joint mortar applied.

The homeowners were delighted with the transformation, and now have a patio that is not only looking beautiful again, but is actually better than when it was new.

Their neighbour was so impressed that they approached CR Services and booked them to carry out the same durable treatment to their patios.

Patios & Terraces

Type of Stone
Indian Sandstone

Type of Paving
Slabs/Flags

Call CR Services

Office: **0161 905 3497**

Mobile: **0781 844 8330**

www.patior refurbishment.co.uk



CRSERVICES