

Patio Refurbishment & All Paving Maintenance



Case Study

Yorkstone Driveway & Patio, Nantwich, Cheshire

This substantial natural Yorkstone driveway in Nantwich, together with a patio and pathways, was looking extremely tired with the original sand and cement grout cracking, and in some areas, coming out completely and leaving unsightly gaps. Looking to refurbish these areas, the homeowners did considerable on-line research to find a reliable paving contractor, who would replace the failed grouting with a high performance paving mortar, capable of withstanding the continual movements of the family vehicles.

Following their research, they contacted paving specialists CR Services, who recommended GftK vdw 850+, a high performance, non-staining, 2-part epoxy paving mortar from NCC Streetscape. This is tough and durable and well capable of withstanding the heavy loadings and exposure to deicing salts etc. on the driveway.

The crew from specialist paving contractors, CR Services, raked out the old failed jointing and all areas were jet-washed and cleaned using NCC Black Spot & Green Growth Remover, which removes unsightly green staining and the hard to remove black lichen deposits.

The homeowners were delighted with their finished patio and in particular the driveway, which can now be used safely without fear of being damaged by the family cars in the future.

Domestic Driveways

Type of Stone
Yorkstone (Sandstone)

Type of Paving
Natural Stone Slabs

Call CR Services
Office: **0161 905 3497**
Mobile: **0781 844 8330**

www.patiorefurbishment.co.uk



CRSERVICES